DEPARTMENT OF PUBLIC WORKS
SUMMARY OF OPERATIONS

FOR NOVEMBER 2016

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected
- Water sampling completed
- Utility work orders: 26
- New meters installed: 17 – 5/8" residential
- Meters replaced: 8 – 5/8" residential
- Registers replaced: 8
- ERTs replaced: 8
- Water leaks repaired:
    - 250 N Snow Canyon Dr #60 – split poly
    - 571 E Mesa Vista Drive

Sewer Collection System

- Sewer Lift Station, weekly maintenance completed
- Sewer Mains Jetted: none this month
- Sewer Manhole Inspections: 481 manholes

Storm Drain Collection System

- Cleared debris from storm grates and culvert inlets
- Performed weekly inspections of yard facilities to reduce pollution risk
- Potholed utilities for storm drain projects under design

Street Maintenance

- Road base used for street and shoulder repairs: 4 tons
- Asphalt used for street and shoulder repairs: 3 tons
- Concrete poured: none
- Signage: 0 new signs
- Signage: 6 sign replaced
- Crack Sealing: Applied 14,100 pounds of material
- Street sweeping: none this month
- Sweeper tailings hauled to landfill: none this month
- Asphalt waste hauled to Western Rock: none this month

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout city
- Herbicide sprayed: none this month

Utility Locating (Blue Stakes)

- Locate requests: 118
- Hours Logged: 61 hours

Inspection

- Active projects: RVU, 400 East, Indigo Trails Ph1, Taviawk, Silver Sage Ph 1 & 2, Sentierre Ph 1, Shadow Canyon Phase 3
- Hours Logged: 92 hours

Training

- Weekly safety meetings
- Shiloh and Travis attended Fundamentals of Water Distribution

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters
- Staff and department meetings
- Inventory management
- Obtaining GPS points for GIS mapping
- Assist with fleet maintenance as needed

