DEPARTMENT OF PUBLIC WORKS SUMMARY OF OPERATIONS

For February 2019

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected
- Water sampling completed, tested 12 locations for total coliform bacteria and chlorine residuals, all results met water quality standards.
- Utility/billing work orders: 32
- New meters installed: 23 – 5/8" residential
- Registers: Changed out 0 faulty registers
- ERT's: Changed 0 faulty ERT's
- Meters replaced: 0 – 5/8" residential
- Electronic meter reading registers and antennas replaced: 0
- Water leaks repaired:
    - 195 N 200 E (Pulled new Service)
- Drained Taviawk Tank for inspection
- Replaced valve at Taviawk Tank
- Replaced Meter Box Lid at lot 103 in Palisades PH 1
- Completed water shut off list

Sewer Collection System

- Sewer Lift Station, weekly maintenance completed
- Cleaned sewer line on 200 S from 100 E to Main St

Storm Drain Collection System

- Cleared debris from storm grates and culvert inlets
- Performed weekly inspections of Public Works Facility

Street Maintenance

- Road base used for street and shoulder repairs: 1 ton
- Asphalt used for street and shoulder repairs: 0 tons
- Concrete repaired sidewalk: 0 Cubic yards
- Crack Seal material used: 1200 lbs
- Repaired/ Replaced street signs: 1
- Collected data for Sign Management Program
- Installed Bike signs throughout the city for the Veyo Bike Loop
- Street sweeping: 55 hours logged covering 117.6 lane miles.
- Sweeper tailings hauled to landfill: 0 tons
- Hauled broken asphalt from street repairs: 0 loads
- Hauled broken concrete from street repairs: 0 load

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout the city.

Utility Locating (Blue Stakes)

- Locate requests: 150 logging 57 hours

Inspection

- Performed Inspections of active projects

Training

- Weekly safety training with crew
- Rural Water Conference- Travis, Page & Justin attended Sewer Operator Level 4 training with Exam
  Brycson attended Water Operator Level 2 training & took an Exam

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters
- Staff and department meetings
- Inventory management-moved and organizing equipment and parts
- Assist in obtaining GPS points to update Ivins City GIS mapping
- Removed saturated clay & imported fill to establish grade at Ivins Reservoir for new bathroom facility
- Assist with Fleet Maintenance as needed

