DEPARTMENT OF PUBLIC WORKS
SUMMARY OF OPERATIONS

For MARCH 2019

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected
- Water sampling completed, tested 12 locations for total coliform bacteria and chlorine residuals, all results met water quality standards.
- Utility/billing work orders: 15
- New meters installed: 18 – 5/8" residential
- Registers: Changed out 11 faulty registers
- ERT's: Changed 9 faulty ERT's
- Meters replaced: 5 – 5/8" residential
- Electronic meter reading registers and antennas replaced: 0
- Water leaks repaired: 0
- Covered and Caped old 6" line at 330 w Center St
- Replaced Meter lid at 615 S 75 E
- Replaced check valve at 280 W 100 S
- Completed 12 Read & Leave on W/O's
- Completed Monthly Water shut off's and turn on's

Sewer Collection System

- Sewer Lift Station, weekly maintenance completed

Storm Drain Collection System

- Cleared debris from storm grates and culvert inlets
- Performed weekly inspections of Public Works Facility

Street Maintenance

- Road base used for street and shoulder repairs: 9 ton
- Asphalt used for street and shoulder repairs: 1 tons
- Concrete repaired sidewalk: 1 Cubic yards
- Crack Seal material used: 9520 lbs
- Collected data for Sign Management Program
- Street sweeping: 60 hours logged covering 101.6 lane miles.
- Sweeper tailings hauled to landfill: 26.76 tons
- Hauled broken asphalt from street repairs: 1 loads
- Hauled broken concrete from street repairs: 2 load

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout the city.

Utility Locating (Blue Stakes)

- Locate requests: 134 logging 39 hours

Inspection

- Performed Inspections of active projects

Training

- Weekly safety training with crew

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters
- Staff and department meetings
- Inventory management-moved and organizing equipment and parts
- Assist in obtaining GPS points to update Ivins City GIS mapping
- Backfilled footings and graded for slabs at Ivins Reservoir for new bathroom facility
- Assist with Fleet Maintenance as needed

