DEPARTMENT OF PUBLIC WORKS
SUMMARY OF OPERATIONS

For March 2021

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected
- Water sampling completed: 12 locations tested for total coliform bacteria and chlorine residuals, which meet our water quality standards.
- Utility/billing work orders: 28
- New meters installed 5/8" residential: 37
- Registers: Changed out faulty registers: 15
- ERT's: Changed faulty ERT's: 20
- Meters replaced 5/8" residential: 16
- Completed meter reading, monthly vault and tank inspections, and water samples.
- Water Service installed or repaired: 6
    - Relocated water service at 1010 E Anillo Ct.
    - Repaired water service leak at 520 S 75 E
    - Repaired water service leak at 1500 E Split Rock Dr #127
    - Repaired and Relocated water service at 65 S Posado Ct.
    - Replaced 2 inch Gate Value at the 200 W 400 S PRV Vault
    - Removed 2- 6 inch main line stubs and 2- 10 x 6 inch tees on Snow Canyon Parkway no longer in service.

Sewer Collection System

- Sewer Lift Station: weekly maintenance completed.
- Inspected 456 Sewer manholes

Street Maintenance

- Road base used for street and shoulder repairs: 8 tons
- Asphalt used for street and shoulder repairs: 45 tons
- Concrete repaired sidewalk & ADA Ramps: 0 Cubic yard
- Crack Seal material used: 5,000 lbs.
- Street signs repaired/replaced: 2
- Street sweeping: 141 hours logged covering 232.31 lane miles.
- Sweeper tailings hauled to landfill: 0 tons
- Hauled away broken asphalt from street repairs to Western Rock recycling: 0 loads
- Hauled away broken concrete from street repairs to recycling center: 0 loads

Storm Drain Collection System

- Cleaned storm grates, removed sediment and debris from culvert inlets
- Performed weekly Public Works Facility Storm Water Inspection

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city
- Trimmed bushes and tree branches in various locations throughout the city
- Herbicide sprayed on the right-of-ways throughout the city: 320 gallons

Utility Locating (Blue Stakes)

- Locate requests: 236, logging 60 hours

Inspection

- Performed Inspections of active projects

Training

- Weekly safety training with crew
- Rural Water Conference at the Dixie Center- Matt, Page, Ray, Justin D. and Justin B. attended

Miscellaneous

- Maintenance of equipment and public works facilities
- Saturday dumpsters
- Staff and department meetings
- Inventory management- moved and organizing equipment and parts
- Assist in obtaining GPS points to update Ivins City mapping
- Assist with Fleet Maintenance as needed

