DEPARTMENT OF PUBLIC WORKS SUMMARY OF OPERATIONS

For May 2026

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected.
- Completed meter reading, monthly vault and tank inspections, and water samples.
- Water sampling completed: 12 locations tested for total coliform bacteria and chlorine residuals, which meet our water quality standards.
- Utility/billing work orders: 14
- Public Works Service Requests: 11
- Metering Equipment:
    - Meter Registers, found faulty and replaced: 38
    - Meter Antennas, found faulty and replaced: 38
    - Meter bodies, replaced 5/8" residential: 38
    - New meters, installed 5/8" residential: 8
- Pull new service lines that were leaking at 2 locations: 250 N Snow Canyon Dr #18 and 320 S 300 W.
- Repaired water main at 2 locations: 20 E 100 N and 473 W Tearasinab Way.

Sewer Collection System

- Performed weekly maintenance on Sewer Lift Station and Dosing Station.
- Performed weekly inspections on the Dosing Station at Coyote Gulch.
- Performed weekly inspection for H2S gas at 200 N Kwavasa manhole.
- Repaired manhole at 980 E Center St.
- Raised manhole lid at 279 S Puerto Dr.

Street Maintenance

- Road base used for street and shoulder repairs: 0 tons of road base and 0 yards of concrete to repair streets/shoulder due to water leaks.
- Asphalt used for street and shoulder repairs: 0
- Crack seal material applied: 12,480 Pounds mostly to fix trip/bike hazards.
- Street signs repaired/replaced: 0 street signs.
- Street lights repaired: 3 street lights.
- Street sweeping: 123 hours logged covering 175.89 lane miles.
- Sweeper tailings hauled to landfill: 0
- Hauled broken concrete from street repairs to recycling center: 0 loads.
- Hauled broken Asphalt from street repairs to recycling center: 0 loads.

Storm Drain Collection System

- Cleaned storm grates, removed sediment and debris from culvert inlets.
- Performed weekly Public Works Facility Storm Water Inspection.

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout the city.
- Sprayed approximately 0 gallons of herbicide on city right-of-way.

Utility Locating (Blue Stakes)

- Locate requests: 184 logging 73 hours.

Inspection

- Assist with inspections as needed.

Training

- Weekly safety training with crew.
- Crew attended a safety training at the Dixie Convention Center (Get your head in the game).

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters.
- Staff and department meetings.
- Moving and organizing equipment and parts (inventory).
- Assist in obtaining GPS points to update Ivins City mapping.

Fleet Maintenance

- Assisted with maintenance as needed.

