DEPARTMENT OF PUBLIC WORKS SUMMARY OF OPERATIONS

For June 2026

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected.
- Completed meter reading, monthly vault and tank inspections, and water samples.
- Water sampling completed: 12 locations tested for total coliform bacteria and chlorine residuals, which meet our water quality standards.
- Utility/billing work orders: 20
- Public Works Service Requests: 15
- Metering Equipment:
    - Meter Registers, found faulty and replaced: 0
    - Meter Antennas, found faulty and replaced: 0
    - Meter bodies, replaced 5/8" residential: 0
    - New meters, installed 5/8" residential: 8
- Pull new service lines that were leaking at 3 locations: 465 W Tenaya dr, 471 E Ridgeview Cir, 147 W 520 S.
- Repaired water main at 2 locations: 761 S 220 E, 206 W Tearasinab Way.
- Completed 182 fire hydrant inspections.
- Cleaned valve cans an exercised 255 valves.

Sewer Collection System

- Performed weekly maintenance on Sewer Lift Station and Dosing Station.
- Performed weekly inspections on the Dosing Station at Coyote Gulch.
- Performed weekly inspection for H2S gas at 200 N Kwavasa manhole.

Street Maintenance

- Road base used for street and shoulder repairs: 9 tons of road base and 2 yards of concrete to repair streets/shoulder due to water leaks.
- Asphalt used for street and shoulder repairs: 6 tons.
- Crack seal material applied: 0 Pounds mostly to fix trip/bike hazards.
- Street signs repaired/replaced: 0 street signs.
- Street lights repaired: 5 bollards lights and 2 street lights.
- Street sweeping: 44 hours logged covering 86 lane miles.
- Sweeper tailings hauled to landfill: 44.65 tons.
- Hauled broken concrete from street repairs to recycling center: 6 loads.
- Hauled broken Asphalt from street repairs to recycling center: 7 loads.

Storm Drain Collection System

- Cleaned storm grates, removed sediment and debris from culvert inlets.
- Performed weekly Public Works Facility Storm Water Inspection.

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout the city.
- Sprayed approximately 400 gallons of herbicide on city right-of-way.

Utility Locating (Blue Stakes)

- Locate requests: 238 logging 64 hours.

Inspection

- Assist with inspections as needed.

Training

- Weekly safety training with crew.

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters.
- Staff and department meetings.
- Moving and organizing equipment and parts (inventory).
- Assist in obtaining GPS points to update Ivins City mapping.
- Assist with animal shelter expansion.

Fleet Maintenance

- Assisted with maintenance as needed.

