DEPARTMENT OF PUBLIC WORKS
SUMMARY OF OPERATIONS

For August 2026

Water Distribution System

- Master meters, PRVs, Pump Stations, Tanks inspected.
- Completed meter reading, monthly vault and tank inspections, and water samples.
- Water sampling completed: 12 locations tested for total coliform bacteria and chlorine residuals, which meet our water quality standards.
- Utility/billing work orders: 28
- Public Works Service Requests: 35
- Metering Equipment:
    - Meter Registers, found faulty and replaced: 7
    - Meter Antennas, found faulty and replaced: 49
    - Meter bodies, replaced 5/8" residential: 7
    - New meters, installed 5/8" residential: 10
- Pull new service lines that were leaking at 6 locations: 124 S Otra, 1500 E Split Rock Dr #93, 130 N Park Ave Way, 418 W 280 S, 465 W Tenaya Dr, 257 S 230 W
- Repaired water main at 1 locations: 33 W 530 S
- Repaired 3 fire hydrants and replaces 1 that couldn't be repaired.
- Replaces angle stops at 6 locations: 554 N Summit Ridge Dr, 140 N Tuacahn Dr #28, 315 E 1060 S, 86 S Docena Dr, 145 E 200 S, 355 E 200 S
- Replaced vale at 1 location: 375 E 1060 S
- Assisted DB Utility by locating water meters and cleaning meter boxes, helped facilitate the completion of approximately 50% of the City's water meter replacement project.

Irrigation System

Sewer Collection System

- Performed weekly maintenance on Sewer Lift Station and Dosing Station.
- Performed weekly inspections on the Dosing Station at Coyote Gulch.
- Performed weekly inspection for H2S gas at 200 N Kwavasa manhole.

Street Maintenance

- Road base used for street and shoulder repairs: 6.25 tons of road base and 4.25 yards of concrete to repair streets/shoulder due to water leaks.
- Asphalt used for street and shoulder repairs: 0 tons.
- Crack seal material applied: 0 Pounds mostly to fix trip/bike hazards.
- Street signs repaired/replaced: 0 street signs.
- Street sweeping: 26 hours logged covering 50 lane miles.
- Sweeper tailings hauled to landfill: 0 tons.
- Hauled broken concrete from street repairs to recycling center: 0 loads.

- Hauled broken Asphalt from street repairs to recycling center: 0 loads.

Storm Drain Collection System

- Cleaned storm grates, removed sediment and debris from culvert inlets.
- Performed weekly Public Works Facility Storm Water Inspection.
- Cleaned and inspected 184 inlet boxes and removed approximately 1,200 cubic feet of sediment and debris.

Vegetation Control in Right-of-Way

- Cleared weeds and trash in various locations throughout city.
- Trimmed bushes and tree branches in various locations throughout the city.
- Sprayed approximately 200 gallons of herbicide on city right-of-way.

Utility Locating (Blue Stakes)

- Locate requests: 110 logging 41 hours.

Inspection

- Assist with inspections as needed.

Training

- Weekly safety training with crew.

Miscellaneous

- Maintenance of equipment and public works facilities.
- Saturday dumpsters.
- Staff and department meetings.
- Moving and organizing equipment and parts (inventory).
- Assist in obtaining GPS points to update Ivins City mapping.

Fleet Maintenance

- Assisted with maintenance as needed.

Crew Labor Analysis

